



217/782-6761

EPA Region 5 Records Ctr.



386170

Refer to: 199055⁵010 -- Williamson County
Marion/Pernia - Treat
ILD 063698971

January 29, 1986

Mr. Rudy Bond
Pernia - Treat of Illinois, Inc.
Post Office Box 99
Marion, Illinois 62959

Dear Mr. Bond:

On January 13, 1986, your facility was inspected by Gerald E. Steele of the Illinois Environmental Protection Agency. The purpose of this inspection was to determine your facility's compliance with the apparent violations cited in the August 27, 1985 Compliance Inquiry Letter. As a result of the inspection, the apparent violations of Sections 722.134 and 722.140 have been resolved.

If you have any questions, please contact Gerald E. Steele at 618/997-4371.

Sincerely,

Mark A. Haney, Manager
Facilities Compliance Unit
Compliance Monitoring Section
Division of Land Pollution Control

MAH:BF:cm:2/129

cc: Division File ✓
Southern Region
Bruce Carlson
Pat McCarthy
Bur Filson

RCRA INSPECTION REPORT
FORM B - Generator Inspection*

General Information*

USEPA Number: 1 4 0 0 6 3 6 9 8 9 7 1 IEPA Number: 1 9 9 0 5 5 0 1 C⁵

Major Facility: ~~YES/NO~~ Notified As: Generator Regulated As: Small Quantity Gen

(A) Facility Name: Perma-Treat of Illinois, Inc.

(B) Street: P.O. Box 99 N. Carbon and Ind. Park Drive

(C) City: Marion (D) State: Illinois (E) Zip Code: 62959

(F) Phone: 618/997-5646 (G) County: Williamson

Region: S (H) Date of Inspection: 01/13/86 Time: (From) 1:30 P (TO) 2:30 P

Type of Inspection: ISS RECORD REVIEW SAMPLING CITIZEN COMPLAINT OTHER

F/U 08/08/85 (Date of Initial Inspection)

(I) Weather Conditions: Sunny, 35°

Area	Section	Class I	Class II

TOTAL Class I's & II's

(J) Person(s) Interviewed	Title	Telephone
<u>Mr. Rudy Bond</u>	<u>President</u>	<u>618/997-5646</u>
<u>Ms. Carolyn Bond</u>	<u>Sec-Treas.</u>	<u>618/997-5646</u>

(K) Inspection Participants	Agency/Title	Telephone
<u>Gerald E Steele</u>	<u>IEPA/EPS</u>	<u>618/997-4371</u>

(L) Preparer Information	Agency/Title	Telephone
Name: <u>Gerald E Steele</u>	<u>IEPA/EPS</u>	<u>618/997-4371</u>

*Do not use this form if Generator is also a treatment, storage, and/or disposal facility.
Complete form "A" if the Generator is also a TSD facility.

RECEIVED

JAN 28 1986

RCRA INSPECTION REPORT
FORM B - Generator Inspection*

General Information*

USEPA Number: 140063698971 IEPA Number: 199055801C
~~Major Facility:~~ YES/NO Notified As: Generator Regulated As: Small Quantity Gen
 (A) Facility Name: Perma-Treat of Illinois Inc.
 (B) Street: P.O. Box 99 N. Carbon & Ind. Park Drive
 (C) City: Marion (D) State: Ill (E) Zip Code: 62959
 (F) Phone: 618/992-5646 (G) County: Williamson
 Region: S (H) Date of Inspection: 01/13/86 Time: (From) 1:00 P (TO) 2:00 P
 Type of Inspection: ISS RECORD REVIEW SAMPLING CITIZEN COMPLAINT OTHER
 F/U 08/08/85 (Date of Initial Inspection)
 (I) Weather Conditions: Sunny, 50°

Area	Section

Class I	Class II

TOTAL Class I's & II's

RECEIVED

FEB 10 1986

IEPA-DLPO

(J) Person(s) Interviewed	Title	Telephone
<u>Mr. Rudy Bond</u>	<u>Pres.</u>	<u>618/992-4371</u>
<u>Ms. Caroline Bond</u>	<u>Sec. Tres.</u>	<u>618/992-4371</u>
(K) Inspection Participants	Agency/Title	Telephone
<u>Gerald F. Steele</u>	<u>IEPA/EPs</u>	<u>618/992-4371</u>
(L) Preparer Information	Agency/Title	Telephone
Name: <u>Gerald F. Steele</u>	<u>IEPA/EPs</u>	<u>618/992-4371</u>

*Do not use this form if Generator is also a treatment, storage, and/or disposal facility.
 *Complete form "A" if the Generator is also a TSD facility.



ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS
INTER-OFFICE CORRESPONDENCE

DATE: Jun. 13, 1986

MEMO TO: File

FROM: G. E. Steele DLPC/FOS Southern Region - Marion

SUBJECT: Williamson COUNTY - D.L.P.C. Inspection

Marion / Parma-Treat

Site No.: 199055010 ILD 063698971

GENERAL REMARKS: All waste has been removed from this facility Sept. 29, 1985.
They have only generated one drum of waste since this date.
The yellow hazardous waste sticker has been applied to this drum.
This site has claimed the small quantity generator exemption. They have created a whole set of documents

INTERVIEW: that was toward compliance with generator standards
Two tanks to hold collected run-off which is
circulated back thru their process have been placed
near the treatment cylinder building. Approx 20,000 gallons of
contaminated water was in holding, which would be reused
within 3 weeks according to Rudy Bond, Pres.

DIAGRAM: A roof is being planned to eliminate most of
this water.

RECEIVED

FEB 10 1986

IEPA-DLPC



ENVIRONMENTAL PROTECTION AGENCY STATE OF ILLINOIS
INTER-OFFICE CORRESPONDENCE

DATE: Jan. 13, 1986

MEMO TO: File

FROM: G. E. Steele

SUBJECT: Williamson COUNTY - D.L.P.C. Inspection

Morrison / Perma-Treat

Site No.: 199 055 0010 ILD063698971

GENERAL REMARKS: A follow-up inspection of this plant which treats wood with a copper-chrome-arsenic process was conducted to verify their small quantity generator status. 33 drums of waste were shipped on 9-24-85. This shipment covered their comprehensive clean-out of the plant.

INTERVIEW: only one drum of waste was on site. A complete set of generator documents was generated. A preliminary review was conducted, and corrective recommendations made.

DIAGRAM: Two 16,000 gallon tanks are been installed next to the treatment cylinder. This is to hold the contaminated stormwater runoff previously held in the tank dikes. About 29,000 gallons was collected to be recycled back to the process. Mr. Bird estimated this could be worked back in within 3 weeks.

RECEIVED

MAR 11 1986

ITD/ELC

RECEIVED
FEB 10 1986
IEPA-DLPC

FOLLOW-UP INSPECTION

DATE: Jan. 13, 1986
TO: Bur Elson HWRC, FACILITIES COMPLIANCE UNIT
FROM: G. E. Steele, S Region
SUBJECT: Marion / Perma-Treat Williamson
(Facility Name) (County)
IL 0063698971 199055010
(USEPA ID Number) (State ID Number)

08/08/85 (Date of Initial Inspection)

On 01/13/86 a follow-up inspection was completed, resolving the following violations:

AREA	SECTION	CLASS
<u>other</u>	<u>722.134</u>	<u>II</u>
<u>other</u>	<u>722.140</u>	<u>II</u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

COMMENTS: They have generated a complete set of generator documents.
only one drum of waste is on site.

RECEIVED
JAN 28 1986
IEPA-DLEC

FOLLOW-UP INSPECTION

DATE: January 15, 1986
TO: Burkison HWRC, FACILITIES COMPLIANCE UNIT
FROM: G.E. Steele, Southern Region
SUBJECT: Maxim / Perama - Treat Williamson
(Facility Name) (County)

ILD 063 698971 19905505010
(USEPA ID Number) (State ID Number)

08/08/85 (Date of Initial Inspection)

On 01/19/86 a follow-up inspection was completed, resolving the following violations:

AREA	SECTION	CLASS
<u>Other</u>	<u>722.134</u>	<u>II</u>
<u>Other</u>	<u>722.140</u>	<u>II</u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>
<u> </u>	<u> </u>	<u> </u>

COMMENTS: Small Quantity Generator Status Confirmed, All Generator requirements
are being met even though they are currently a SQG.